

NOTE: Remove plastic film from battery prior to mounting thermometer.

MOUNTING DIRECTIONS

- 1. Attach suction cups and mount Digital Thermometer and probe in desired location.
- 2. Press power button to activate unit.
- 3. Slide Fahrenheit/Celsius selector switch to desired reading.
- 4. Depress power button for three seconds to turn unit off.
- Remove battery for long-term storage.
 Replacement battery: LR44, 1.5V
 Accuracy ±1.5°F

